



2008-03

NOTIFICATION OF INTENT TO REMOVE ASBESTOS CONTAINING MATERIALS, OR TO DEMOLISH

This form will be considered incomplete until all information is supplied below. If any changes are made after the notification is logged with the Agency, an amendment must be filed before work begins or continues. See other side for assistance in completing this form.

OFFICE USE: PROJECT # _____ Fee Rec'd \$ _____ Date Rec'd _____

I. OPERATION CATEGORY	ADVANCED	FEE
	NOTIFICATION PERIOD REQUIRED	
<input checked="" type="checkbox"/> All Demolition Projects	10 working days	\$11
<input type="checkbox"/> Residential Asbestos Project	10 working days	\$11
<input checked="" type="checkbox"/> Asbestos Project: 10 to 259 lf or 48 to 159 sf	10 working days	\$142
<input type="checkbox"/> Asbestos Project: 260 to 999 lf or 160 to 4,999 sf	10 working days	\$283
<input type="checkbox"/> Asbestos Project: 1,000 to 9,999 lf or 5,000 to 49,999 sf	10 working days	\$567
<input type="checkbox"/> Asbestos Project: more than 10,000 lf or more than 50000 sf	10 working days	\$1699
<input type="checkbox"/> Amendments for Project # _____	Prior Notification	Res. \$27 / Others \$57
<input type="checkbox"/> Annual Notification	10 working days	\$1699
<input type="checkbox"/> All Emergencies	Prior Notification	Res. \$57 / Others 2x Fee
<input type="checkbox"/> All Alternate Methods	10 working days	2x Fee

II. CONTRACTOR

Contractor's Name: Fluor Hanford, Incorporated

Certification # _____

Address: P.O. Box 1000 Richland WA 99352
Street City State Zip

Contact: Tom Beam Title: Point of Contact Phone: (509)376-4876

III. JOB SITE

Property Owner: United States Department of Energy, Richland Field Office Phone: (509)376-2347

Address: 815 Jadwin Avenue Richland WA 99352
Street City State Zip

Name of Job Site: MO-384 and MO-922 Trailers

Address: MO-384 & MO-922, 200 East Area, Hanford Site, Richland WA 99352
Street City State Zip

Building/Room Where

Job Will Occur: Asbestos in bathroom flooring in trailer MO-922.

Site Contact: Mike Stevens Title: Project Manager Phone: (509)430-5756

IV. Asbestos "good faith survey" has been conducted? ☒ YES ☐ NO. By whom? Russ D. Smith

Type(s) of asbestos present, if any (Friable, Category I, Category II): Category I

V. Start Date of Removal: June 27, 2008 Date of Completion: September 30, 2008

Approximate Amount of Asbestos to be Removed: _____ Linear Feet 110 Square Feet

Method of Removal and Work Plan Specifications: (Attach description if more room is needed)

Trailer Demolitions: Areas where demolitions will occur will be wetted for dust suppression; fixative may also be used on debris for dust suppression during demolition and waste loading. Traditional demolition and loading equipment will be utilized.

VI. Name of Disposal Site: Basin Disposal Incorporated Phone: (509)544-7703

Diana L. Klages
Your Signature

06/16/08
Date

Approval: BCAA [Signature]

Date: 16 June 08

REMIT FEE & FORM TO: BCAA, 526 S. Clodfelter Road, Kennewick, WA 99336

ADDENDUM TO BCAA "NOTIFICATION OF INTENT TO REMOVE ASBESTOS CONTAINING MATERIALS"

1. TYPE OF NOTIFICATION (O = Original / R = Revised): 0 (D - Demolition / R = Renovation): D

FOR EMERGENCY RENOVATIONS FILL OUT THE REST OF THIS SECTION, OTHERWISE GO TO 2.

Date and Hour of Emergency (MM/DD/YY): N/A

Description of the Sudden, Unexpected Event:

Explanation of How the Event Caused Unsafe Conditions or Serious Disruption of Industrial Operations:

2. FACILITY INFORMATION

Operator: United States Department of Energy

Street Address: MO-384 and MO-922, Hanford Site

Richland, Washington 99352 Contact: Tom Beam

Tel: 376-4876

BUILDING SIZE

Sq. Meter:

Sq. Ft: 3192

No. of Floors: 1

Age in Years: Old

Present Use: Unoccupied

Prior Use: Office Space and Storage

3. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:

Asbestos Good Faith Inspection and Lab Analyses identified 35-45% Chrysotile Asbestos Fibers in Vinyl Flooring.

4. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED RACM IS FOUND OR CATEGORY II NONFRIABLE ACM BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER:

Field activities will be stopped and appropriate notifications will be made before conducting further sampling and analyses or enhancing demolition techniques and controls.

5. SCHEDULED DATES OF DEMO/RENOVATION (MM/DD/YY)

Start: 06/27/08

Completion: 09/30/08

6. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:

Standard industrial demolition equipment will be utilized. Areas will be wetted for dust suppression.

7. WASTE TRANSPORTER (Attach another sheet if there are two transporters)

Name: Fluor Hanford, Inc.

Address: Hanford Site

City: Richland

State: WA

Zip: 99352

Contact Person: Mike Stevens; Project Manager

Telephone: 509-430-5756

8. LOCATION OF WASTE DISPOSAL SITE

Address: 2021 Commercial Avenue

City: Pasco


State: WA

Zip: 99302

9. APPROXIMATE AMOUNT OF RACM TO BE REMOVED AND NONFRIABLE ASBESTOS MATERIAL THAT WILL NOT BE REMOVED. SPECIFY THE AMOUNT BELOW.

	Nonfriable Asbestos Material Not to be Removed Before Demolition		
	RACM to be Removed	Cat I	Cat II
Pipes - Linear Meters (Linear Feet)	See V. of BCAA Form		
Surface Area - Square Meters (Square Feet)	See V. of BCAA Form	110	
Volume RACM Off Facility Component - Cubic Meter			

10. I certify that an individual trained in the provisions of (40 CFR 61, Subpart M) will be on-site during the demolition or renovation and evidence that the required training has been accomplished by this person will be available for inspection during normal business hours.


(Signature of Owner/Operator)

06/16/08
(Date)